

Header

Asbestos Survey for

at

,18 Rochester Row

Footer

TABLE OF CONTENTS

SECTION 1	Survey Summary
SECTION 2	Bulk Identification Report
SECTION 3	Survey Drawings
SECTION 4	Material Assessment: Summary by Floor
SECTION 5	Material Assessment (Photo)
SECTION 6	Survey Recommendations

SECTION ONE

SURVEY SUMMARY

Survey Summary

SECTION TWO

BULK IDENTIFICATION REPORT

Header

Client:		Date Samples Received:	
Client Address:		Date Samples Analysed:	
Site Address:	,18 Rochester Row,,		
Status:	Asbestos Presumed, Inaccessible		
Risk:	Unknown		
F.A.O:			

Bulk Identification Report

Bulk identification table

Level	Room	Location	Asbestos Type	Product Type	Extent
Ground Floor	Hall	Hall	-Specify Asbestos Type-	-Specify Product Type-	0
Ground Floor	Cupboard 1	Cupboard 1 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
Ground Floor	Intake cupboard	Intake cupboard , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
Ground Floor	Lobby	Lobby , No access, Ceiling void	-Specify Asbestos Type-	-Specify Product Type-	0
Ground Floor	Exit	Exit	-Specify Asbestos Type-	-Specify Product Type-	0
Ground Floor	Bin store	Bin store	-Specify Asbestos Type-	-Specify Product Type-	0
1st Floor	Landing	Landing	-Specify Asbestos Type-	-Specify Product Type-	0
1st Floor	Bin store	Bin store	-Specify Asbestos Type-	-Specify Product Type-	0
1st Floor	Corridor 1	Corridor 1	-Specify	-Specify Product	0

Footer

Header

			Asbestos Type-	Type-	
1st Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
1st Floor	Corridor 2	Corridor 2	-Specify Asbestos Type-	-Specify Product Type-	0
1st Floor	Intake cupboard 2	Intake cupboard 2 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
2nd Floor	Landing	Landing	-Specify Asbestos Type-	-Specify Product Type-	0
2nd Floor	Bin store	Bin store	-Specify Asbestos Type-	-Specify Product Type-	0
2nd Floor	Corridor 1	Corridor 1	-Specify Asbestos Type-	-Specify Product Type-	0
2nd Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
2nd Floor	Corridor 2	Corridor 2	-Specify Asbestos Type-	-Specify Product Type-	0
2nd Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
3rd Floor	Landing	Landing	-Specify Asbestos Type-	-Specify Product Type-	0
3rd Floor	Bin store	Bin store	-Specify Asbestos Type-	-Specify Product Type-	0
3rd Floor	Corridor 1	Corridor 1	-Specify Asbestos Type-	-Specify Product Type-	0
3rd Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
3rd Floor	Corridor 2	Corridor 2	-Specify Asbestos Type-	-Specify Product Type-	0
3rd Floor	Intake cupboard 2	Intake cupboard 2 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
4th Floor	Landing	Landing	-Specify Asbestos Type-	-Specify Product Type-	0
4th Floor	Bin store	Bin store	-Specify	-Specify Product	0

Header

4th Floor	Corridor 1	Corridor 1	Asbestos Type- -Specify Asbestos Type-	Type- -Specify Product Type-	0
4th Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
4th Floor	Corridor 2	Corridor 2	-Specify Asbestos Type-	-Specify Product Type-	0
4th Floor	Intake cupboard 2	Intake cupboard 2 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
5th Floor	Landing	Landing	-Specify Asbestos Type-	-Specify Product Type-	0
5th Floor	Bin store	Bin store	-Specify Asbestos Type-	-Specify Product Type-	0
5th Floor	Corridor 1	Corridor 1	-Specify Asbestos Type-	-Specify Product Type-	0
5th Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
5th Floor	Corridor 2	Corridor 2	-Specify Asbestos Type-	-Specify Product Type-	0
5th Floor	Intake cupboard 2	Intake cupboard 2 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
6th Floor	Landing	Landing	-Specify Asbestos Type-	-Specify Product Type-	0
6th Floor	Bin store	Bin store	-Specify Asbestos Type-	-Specify Product Type-	0
6th Floor	Corridor 1	Corridor 1 , Attached to the main ceiling above the suspended ceiling and pipework (possibly as a heat shield), Ceiling boards	-Specify Asbestos Type-	-Specify Product Type-	0
6th Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0

Header

6th Floor	Corridor 2	Corridor 2 , Attached to the main ceiling above the suspended ceiling and pipework (possibly as a heat shield), Ceiling boards	-Specify Asbestos Type-	-Specify Product Type-	0
6th Floor	Intake cupboard 2	Intake cupboard 2 , , Inaccessible	-Specify Asbestos Type-	-Specify Product Type-	0
External	External	External	-Specify Asbestos Type-	-Specify Product Type-	0

Header

SECTION THREE

SURVEY DRAWINGS

Survey Drawings and Documentation

Description of Drawing:

Header

SECTION FOUR

MATERIAL ASSESSMENT: SUMMARY BY FLOOR

Material Assessment : Summary by floor

Material Assessment : Summary by floor

Footer

Header

Sample Date	Level	Room	Location	Product Type	Extent	Asbestos Type	Material Score	Priority Risk Score	Sample And Test Notes	Action	Assessment Type
25/02/2015 00:00:00	Ground Floor	Hall	Hall	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	Ground Floor	Cupboard 1	Cupboard 1 , , Inaccessible	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	Ground Floor	Intake cupboard	Intake cupboard , , Inaccessible	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	Ground Floor	Lobby	Lobby , No access, Ceiling void	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	Ground Floor	Exit	Exit	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	Ground Floor	Bin store	Bin store	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	1st Floor	Landing	Landing	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	1st Floor	Bin store	Bin store	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	1st Floor	Corridor 1	Corridor 1	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	1st Floor	Intake cupboard 1	Intake cupboard 1 , ,	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey

Header

25/02/2015 00:00:00	1st Floor	Corridor 2	Inaccessible Corridor 2	-Specify Product Type-	0	-Specify Asbestos Type-	0	0	- Specify Action-	Management Survey
25/02/2015 00:00:00	1st Floor	Intake cupboard 2	Intake cupboard 2 , , Inaccessible	-Specify Product Type-	0	-Specify Asbestos Type-	0	0	- Specify Action-	Management Survey
25/02/2015 00:00:00	2nd Floor	Landing	Landing	-Specify Product Type-	0	-Specify Asbestos Type-	0	0	- Specify Action-	Management Survey
25/02/2015 00:00:00	2nd Floor	Bin store	Bin store	-Specify Product Type-	0	-Specify Asbestos Type-	0	0	- Specify Action-	Management Survey
25/02/2015 00:00:00	2nd Floor	Corridor 1	Corridor 1	-Specify Product Type-	0	-Specify Asbestos Type-	0	0	- Specify Action-	Management Survey
25/02/2015 00:00:00	2nd Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	-Specify Product Type-	0	-Specify Asbestos Type-	0	0	- Specify Action-	Management Survey
25/02/2015 00:00:00	2nd Floor	Corridor 2	Corridor 2	-Specify Product Type-	0	-Specify Asbestos Type-	0	0	- Specify Action-	Management Survey
25/02/2015 00:00:00	2nd Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	-Specify Product Type-	0	-Specify Asbestos Type-	0	0	- Specify Action-	Management Survey
25/02/2015 00:00:00	3rd Floor	Landing	Landing	-Specify Product Type-	0	-Specify Asbestos Type-	0	0	- Specify Action-	Management Survey
25/02/2015 00:00:00	3rd Floor	Bin store	Bin store	-Specify Product	0	-Specify Asbestos	0	0	- Specify	Management Survey

Header

25/02/2015 00:00:00	3rd Floor	Corridor 1	Corridor 1	Type- -Specify Product	0	Type- -Specify Asbestos	0	0	Action- - Specify	Management Survey
25/02/2015 00:00:00	3rd Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	Type- -Specify Product Type-	0	Type- -Specify Asbestos Type-	0	0	Action- - Specify	Management Survey
25/02/2015 00:00:00	3rd Floor	Corridor 2	Corridor 2	Type- -Specify Product	0	Type- -Specify Asbestos	0	0	Action- - Specify	Management Survey
25/02/2015 00:00:00	3rd Floor	Intake cupboard 2	Intake cupboard 2 , , Inaccessible	Type- -Specify Product Type-	0	Type- -Specify Asbestos Type-	0	0	Action- - Specify	Management Survey
25/02/2015 00:00:00	4th Floor	Landing	Landing	Type- -Specify Product	0	Type- -Specify Asbestos	0	0	Action- - Specify	Management Survey
25/02/2015 00:00:00	4th Floor	Bin store	Bin store	Type- -Specify Product	0	Type- -Specify Asbestos	0	0	Action- - Specify	Management Survey
25/02/2015 00:00:00	4th Floor	Corridor 1	Corridor 1	Type- -Specify Product	0	Type- -Specify Asbestos	0	0	Action- - Specify	Management Survey
25/02/2015 00:00:00	4th Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	Type- -Specify Product Type-	0	Type- -Specify Asbestos Type-	0	0	Action- - Specify	Management Survey
25/02/2015 00:00:00	4th Floor	Corridor 2	Corridor 2	Type- -Specify Product	0	Type- -Specify Asbestos	0	0	Action- - Specify	Management Survey
25/02/2015 00:00:00	4th Floor	Intake cupboard	Intake cupboard 2	Type- -Specify Product	0	Type- -Specify Asbestos	0	0	Action- - Specify	Management Survey

Footer

Header

		2	, , Inaccessible	Type-		Type-				Action-	
25/02/2015 00:00:00	5th Floor	Landing	Landing	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	5th Floor	Bin store	Bin store	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	5th Floor	Corridor 1	Corridor 1	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	5th Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	5th Floor	Corridor 2	Corridor 2	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	5th Floor	Intake cupboard 2	Intake cupboard 2 , , Inaccessible	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	6th Floor	Landing	Landing	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	6th Floor	Bin store	Bin store	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	6th Floor	Corridor 1	Corridor 1 , Attached to the main ceiling above the	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey

Header

			suspended ceiling and pipework (possibly as a heat shield), Ceiling boards								
25/02/2015 00:00:00	6th Floor	Intake cupboard 1	Intake cupboard 1 , , Inaccessible	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	6th Floor	Corridor 2	Corridor 2 , Attached to the main ceiling above the suspended ceiling and pipework (possibly as a heat shield), Ceiling boards	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	6th Floor	Intake cupboard 2	Intake cupboard 2 , , Inaccessible	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey
25/02/2015 00:00:00	External	External	External	-Specify Product Type-	0	-Specify Asbestos Type-	0	0		- Specify Action-	Management Survey

Header

SECTION FIVE

MATERIAL ASSESSMENT (PHOTO)

Survey Summary

Assessment Details

Survey Summary

Room	Hall
Level	Ground Floor
Location	Hall
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Cupboard 1
Level	Ground Floor
Location	Cupboard 1 , , Inaccessible

Footer

Header

Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Intake cupboard
Level	Ground Floor
Location	Intake cupboard , , Inaccessible
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Footer

Header

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Lobby
Level	Ground Floor
Location	Lobby , No access, Ceiling void
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Exit
Level	Ground Floor
Location	Exit
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-

Footer

Header

Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Bin store
Level	Ground Floor
Location	Bin store
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Landing
Level	1st Floor
Location	Landing
Surveyor	Tersus

Footer

Header

Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Bin store
Level	1st Floor
Location	Bin store
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Footer

Header

Date of Action:

Survey Summary

Room	Corridor 1
Level	1st Floor
Location	Corridor 1
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Intake cupboard 1
Level	1st Floor
Location	Intake cupboard 1 , , Inaccessible
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	

Footer

Header

Notes	Inaccessible room or item, maintain presumption of asbestos until accessed
-------	--

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Corridor 2
Level	1st Floor
Location	Corridor 2
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Intake cupboard 2
Level	1st Floor
Location	Intake cupboard 2 , , Inaccessible
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey

Footer

Header

Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Landing
Level	2nd Floor
Location	Landing
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Header

Survey Summary

Room	Bin store
Level	2nd Floor
Location	Bin store
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Corridor 1
Level	2nd Floor
Location	Corridor 1
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Header

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Intake cupboard 1
Level	2nd Floor
Location	Intake cupboard 1 , , Inaccessible
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Corridor 2
Level	2nd Floor
Location	Corridor 2
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0

Header

Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Intake cupboard 1
Level	2nd Floor
Location	Intake cupboard 1 , , Inaccessible
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Landing
------	---------

Footer

Header

Level	3rd Floor
Location	Landing
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Bin store
Level	3rd Floor
Location	Bin store
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Footer

Header

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Corridor 1
Level	3rd Floor
Location	Corridor 1
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Intake cupboard 1
Level	3rd Floor
Location	Intake cupboard 1 , , Inaccessible
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-

Footer

Header

Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Corridor 2
Level	3rd Floor
Location	Corridor 2
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Intake cupboard 2
Level	3rd Floor
Location	Intake cupboard 2 , , Inaccessible
Surveyor	Tersus

Footer

Header

Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Landing
Level	4th Floor
Location	Landing
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Footer

Header

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Bin store
Level	4th Floor
Location	Bin store
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Corridor 1
Level	4th Floor
Location	Corridor 1
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0

Footer

Header

Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Intake cupboard 1
Level	4th Floor
Location	Intake cupboard 1 , , Inaccessible
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Corridor 2
Level	4th Floor
Location	Corridor 2
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00

Footer

Header

Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Intake cupboard 2
Level	4th Floor
Location	Intake cupboard 2 , , Inaccessible
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Action: -Specify Action-

Footer

Header

Date of Action:

Survey Summary

Room	Landing
Level	5th Floor
Location	Landing
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Bin store
Level	5th Floor
Location	Bin store
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	

Footer

Header

Notes	No Action Required
-------	--------------------

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Corridor 1
Level	5th Floor
Location	Corridor 1
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Intake cupboard 1
Level	5th Floor
Location	Intake cupboard 1 , , Inaccessible
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-

Footer

Header

Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Corridor 2
Level	5th Floor
Location	Corridor 2
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Footer

Header

Room	Intake cupboard 2
Level	5th Floor
Location	Intake cupboard 2 , , Inaccessible
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Landing
Level	6th Floor
Location	Landing
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Header

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Bin store
Level	6th Floor
Location	Bin store
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Corridor 1
Level	6th Floor
Location	Corridor 1 , Attached to the main ceiling above the suspended ceiling and pipework (possibly as a heat shield), Ceiling boards
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-

Header

Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Intake cupboard 1
Level	6th Floor
Location	Intake cupboard 1 , , Inaccessible
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Footer

Header

Room	Corridor 2
Level	6th Floor
Location	Corridor 2 , Attached to the main ceiling above the suspended ceiling and pipework (possibly as a heat shield), Ceiling boards
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	Intake cupboard 2
Level	6th Floor
Location	Intake cupboard 2 , , Inaccessible
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	Asbestos Presumed, Inaccessible
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	Inaccessible room or item, maintain presumption of asbestos until accessed

Footer

Header

Assessment Details

Action: -Specify Action-

Date of Action:

Survey Summary

Room	External
Level	External
Location	External
Surveyor	Tersus
Date	25/02/2015 00:00:00
Review Date	26/02/2015 00:00:00
Status	No Asbestos Detected
Assessment Type	Management Survey
Product Type	-Specify Product Type-
Extent	0
Damage	-Specify Damage-
Surface Treatment	-Specify Treatment-
Asbestos Type	-Specify Asbestos Type-
Material Score	0
Priority Score	0
Risk Assessment Score	0
Sample and Test Notes	
Notes	No Action Required

Assessment Details

Action: -Specify Action-

Date of Action: