

Link to Other Buildings: No

FA Service Report Sheet

IPS Ltd. 124 City Road, London, EC1V 2NX Tel: 0333 320 8035

Building Name:		Ema	anuel Ho	ouse							
Report Sheet No:		1963				Date:	ate: 23/10/2024				
Client Name		The Lord Mayor & Citizens of Westminster C/o Firstport Group Ltd									
Site Name:		Emanuel House									
Site Address:		18 F	Rocheste	er Row SW1	P 1BS						
Contract No:											
Panel Manufacturer:	KEN	KENTEC									
Model:	Sync	ro A	\S								
Panel In Fault	On Ar	rrival?		No		Pa	Panel In Fault On Con		npletion?	No	
all panel functi	ons te	este	d?	No			Pri	nter in	operati	ion?	N/A
C&E Tes				No					•		
				I.							
Correct Mains Is Method?	solatio	on	No			Mains	Mains Isolation Method Info				
Repeater Panel	Fitted	d? No			Rep	Repeater Panel Info					
Networked Pane	l Fitte	d?				Netw	Networked Panel Info				
Battery Location	on:										
Batteries Correct	Size?	? Yes Ir				Info					
Leads & Connectors Satisfactory?		Yes			Info	ıfo					
					Batter	y Size:					
Size					Qu	uantity Date I		stalled			
Battery Reading:											
Battery:			Mains	Charging	Batte	ery	Aux			More Infori	mation
Device Protocol:		POL	.LO								
APOLLO:	XF	P95									
Monitoring: REDCARE											
✓ REDCARE											
Monitoring Further Details:											
Monitoring Line Nu	mhor										
		_									
Monitoring Contrac		U									
Monitoring Station:											

Other Building



FA Service Report Sheet

IPS Ltd. 124 City Road, London, EC1V 2NX Tel: 0333 320 8035

Areas Serviced				
Area	Serviced	Information		

Sounder Tests				
Audibility Test Completed?	No	Result Satisfactory?	No	
Audibility Test Notes:				
Sounder Test Completed?	No	Result Satisfactory?	No	
Sounder Test Notes:				
Sounders:				

General Checks				
Test	Yes/No	Comments		
Are sensors 1m away from vents/AC ducts etc	Yes			
Any storage within 300mm of the ceiling	No			
All sensors have clear spacing of 500mm	Yes			
Any new or existing walls within 500mm of a sensor	No			
Are the sensors over 10 years old	No			
Any structural or occupancy changes to the premises which affect compliance	No			
How many false alarms have occurred in the past 12 months				
Minimum One X callpoint tested per zone	No			
Are callpoints at all exits from floors and the building	No			
Do the callpoints have hinged covers	No			
Zone chart adjacent to the control panel	No			
As installed drawings available	No			

Material Used					
Material	Quantity	Information			

Log Book Completed?	No		
Outstanding Issues:	Yes	If Yes:	See previous reports.
	Flats 20 and 27 tested. All okay		
Other Information:			
	Checked Redcare received signal oka	y.	

Photo Table

I CERTIFY THAT THE ENGINEER HAS ATTENDED SITE AND COMPLETED ALL WORKS TO OUR SATISFACTION

Client Signature:	Client Name:	Billy
Engineer Signature:	Engineer Name:	Jeremy Brookes